


## PRS Bernie Marsdan Left Handed Wiring Diagram 500k Reverse Taper Pots



⏏ = Ground