


## Fender American Jazzmaster Left Handed Wiring Diagram 500k Reverse Taper Pots



Ground Wire from Bridge

⏏ = Ground